


Uva Wellassa University, Sri Lanka  
End Semester Examination – February/March 2012  
SCT 468-2 Computer Aided Design & Manufacturing



Time: Two (02) Hours

Total 04 Questions  
Answer all questions



- 1)
  - I. Define Computer aided manufacturing (CAM). (20 marks)
  - II. List the most important reasons of using CAD systems in the manufacturing environment. Explain them briefly (20 marks)
  - III. Write down 05 different types of features used in design and manufacturing environment. (05 marks)
  - IV. Describe feature-based approach briefly. (25 marks)
  - V. Describe briefly the CAM cycle in feature – based manufacturing environment. (30 marks)
- 2) Identification and grouping of feature entities from a geometric model is known as feature recognition in manufacturing engineering.
  - I. List 05 feature recognition approaches used in manufacturing engineering. (10 marks)
  - II. Explain the graph-based approach using a suitable example. (30 marks)
  - III. Develop a rule by using the logic based approach for the following component. (60 marks)




Fig. 2.1

3)

I. Define Geometry and Topology of an object.

(12 marks)

II. List different types of geometric modeling techniques for representing 3 dimensional objects. Explain them briefly.

(18 marks)

III. Construct the CSG tree for the part shown in Fig. 3.1.

(30 marks)




Fig. 3.1

IV. Check the validity of the part shown in Fig 3.2 using Euler's formula.

(20 marks)




Fig. 3.2

V. Draw the part obtained by applying rotational sweep for the boundary set given in Fig. 3.3.

(20 marks)




Fig. 3.3

4)

I. Describe variant process planning (VPP) briefly.

(15 marks)

II. Write a G- code program for the part in Fig 4.1.

(85 marks)





Fig 4.1

M-Code	Function
M0	Program stop.
M2	End of program.
M3	Spindle ON FWD.
M4	Spindle ON REV.
M5	Spindle OFF.
M8	Coolant ON.
M9	Coolant OFF.
M30	Jump to new program.
M98	Call subprogram.
M99	End subprogram.
M100	Mirror image.
M105	Dry-run, all axes.
M106	Dry-run, NO Z axis.
M107	Dry-run off (cancels M105 or M106).

Modal		Non-Modal	
G-Code	Function	G-Code	Function
G0	Positioning-Rapid Traverse	G4	Dwell
G1	Linear Interpolation-Feed	G5	Ellipse
G2	Circular Interpolation-CW	G9	Exact Stop Check
G3	Circular Interpolation-CCW	G28	Return to Machine Home
G22	Stored Stroke Limit ON	G29	Return from Machine Home
G40	Tool Radius Compensation, Cancel	G31	Probe Move
G41	Tool Radius Compensation (Left)	G45	Mold Rotation
G42	Tool Radius Compensation (Right)	G49	Elbow Milling
G53	Work Coordinate System	G62	Automatic Feed Override for Arcs
G59	Modal Corner Rounding	G63	Automatic Feed Override for Arcs Cancel
G60	Modal Corner Rounding Off	G65	User Macro Single Call
G61	Exact Stop Check Mode	G66	User Macro Modal Call
G64	Cutting Mode (Continuous Path ON)	G67	User Macro Modal Call Cancel
G66	User Macro Modal Call	G68	Coordinate System Rotation
G67	User Macro Modal Call Cancel	G73	Draft Pocket Milling Cycle
G68	Coordinate System Rotation	G75	Frame Milling
G70	Inch Programming	G76	Hole Milling Cycle
G71	MM Programming	G77	Circular Pocket Cycle
G72	Axis Scaling	G78	Rectangular Pocket Cycle
G90	Absolute Programming	G79	Bolt Hole Circle Cycle
G91	Incremental Programming	G80	Cancel Modal Drilling