

Uva Wellassa University, Sri Lanka  
Faculty of Science and Technology  
Science and Technology Degree program  
1<sup>st</sup> Semester Examination – March/April 2013



**SCT 468-2 Computer Aided Design and Manufacturing**

---

Total three (03) Questions

Time: Two (02) Hours

Answer all questions on the question paper itself.

Total mark allocation 300.

---

1.
  - a. What are the drawbacks in the sequential product development process?  
(20 marks)
  - b. What are the advantages of having a simultaneous/integrated product development process?  
(20 marks)
  - c. Explain the needs recognition matrix using an example.  
(20 marks)
  - d. What is conceptual design? How do you select the best concept from a group of possible solutions?  
(40 marks)
2.
  - a. What are the reasons to have an integrated CAD/CAM system?  
(20 marks)
  - b. What is CIM? Give a model for CIM implementation.  
(20 marks)
  - c. Discuss different types of features in CAD.  
(20 marks)
  - d. What is the difference between design features and manufacturing features? Explain your answer using sketches.  
(40 marks)
3.
  - a. What is the difference between G02 and G03 in CNC machine programming? Explain with an example.  
(10 marks)

- b. What are the different methods of inputting a program into a CNC machine? (10 mark)
- c. Write G-Code CNC program for the part shown in Fig.Q03. List of G-Codes and M-Codes are given at the end of the question paper. All dimensions are in inches. Thickness of the part is 0.5 inch. Propose a suitable material for the workpiece and diameters of the tools used. Select a work coordinate system. Write down any other assumed data if any. (80 mark)




Fig.Q03

*Standard M-Codes*

- M00 program stop
- M01 optional stop
- M02 end of program (no rewind)
- M03 spindle CW
- M04 spindle CCW
- M05 spindle stop
- M06 tool change
- M07 mist coolant ON
- M08 flood coolant ON
- M09 flood coolant OFF
- M19 spindle orientation ON
- M30 end program (rewind stop)
- M98 call sub-program
- M99 end sub-program

### *G-Code List Machining Centers*

- G00 positioning (rapid traverse)
- G01 linear interpolation (feed)
- G02 circular interpolation CW
- G03 circular interpolation CCW
- G04 dwell
- G07 imaginary axis designation
- G09 exact stop check
- G10 offset value setting
- G17 XY plane selection
- G18 ZX plane selection
- G19 YZ plane selection
- G20 input in inch
- G21 input in mm
- G22 stored stroke limit ON
- G23 stored stroke limit OFF
- G27 reference point return check
- G28 return to reference point
- G29 return from reference point
- G30 return to 2nd, 3rd & 4th ref. Point
- G31 skip cutting
- G33 thread cutting
- G40 cutter compensation cancel
- G41 cutter compensation left
- G42 cutter compensation right
- G43 tool length compensation + dir
- G44 tool length compensation - dir
- G49 tool length compensation cancel
- G45 tool offset increase
- G46 tool offset decrease
- G47 tool offset double increase
- G48 tool offset double decrease
- G50 scaling OFF
- G51 scaling ON
- G52 local coordinate system setting
- G54 work coordinate system 1 select
- G55 work coordinate system 2 select
- G56 work coordinate system 3 select
- G57 work coordinate system 4 select
- G58 work coordinate system 5 select
- G59 work coordinate system 6 select
- G60 single direction positioning
- G61 exact stop check mode
- G64 cutting mode
- G65 custom macro simple call
- G66 custom macro modal call
- G67 custom macro modal call cancel
- G68 coordinate system rotation ON
- G69 coordinate system rotation OFF
- G73 peck drilling cycle
- G74 counter tapping cycle
- G76 fine boring
- G80 canned cycle cancel
- G81 drilling cycle, spot boring
- G82 drilling cycle, counter boring
- G83 peck drilling cycle
- G84 tapping cycle
- G85,G86 boring cycle
- G87 back boring cycle
- G88,G89 boring cycle
- G90 absolute programming
- G91 incremental programming
- G92 programming of absolute zero point
- G94 per minute feed
- G95 per revolution feed
- G96 constant surface speed control
- G97 constant surface speed control cancel
- G98 return to initial point in canned cycle
- G99 return to Ref point in canned cycle